


RAW

DESCALE THE KETTLE WITH CITRIC ACID

1. TAKE KETTLE
2. HALF FILL WITH WATER
3. BOIL
4. ONCE KETTLE SWITCHES OFF, ADD 2-3 TBSPS OF RAW CITRIC ACID
5. LEAVE TO DISSOLVE FOR 30-60MINS (DEPENDS HOW SERIOUS YOUR LIMESCALE SITUATION IS)
6. POUR OUT & RINSE WELL
7. MAKE A CUP OF TEA



by **FILL**